

From: [Miller, Garyg](#)
To: [Sanchez, Carlos](#); [Meyer, John](#)
Subject: RE: San Jacinto Maintenance Work Plan
Date: Tuesday, March 22, 2016 7:31:00 AM

The report mentions a very low tide after the inspections last week & areas were visible that weren't visible before. When the probing was done last week they were going by feel only & couldn't see the fabric, but they did feel the rock presence, so it was reported as being a thin cap instead of exposed geotextile.

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov

From: Sanchez, Carlos
Sent: Tuesday, March 22, 2016 6:58 AM
To: Meyer, John <Meyer.John@epa.gov>; Miller, Garyg <Miller.Garyg@epa.gov>
Subject: RE: San Jacinto Maintenance Work Plan

Yea, although it mentions that rock aggregate is present, it also states that geotextile is exposed. CAS

From: Meyer, John
Sent: Tuesday, March 22, 2016 6:48 AM
To: Sanchez, Carlos; Miller, Garyg
Subject: Fwd: San Jacinto Maintenance Work Plan

So I have been reporting for days to XA that there has not been any new exposed areas of geotextile. This work plan shows that all the areas have exposed geotextile. Why was there a disconnect here in the reporting? Will need to send a correction to XA today.

Sent from my iPad

John C Meyer
Remedial Branch Chief (6SF-R)
Superfund Division
214.665.6742
214.460.5897 cell

Begin forwarded message:

From: "Miller, Garyg" <Miller.Garyg@epa.gov>
Date: March 21, 2016 at 6:44:22 PM CDT
To: David Keith <dkeith@anchoragea.com>
Cc: Philip J Slowiak <Philip.Slowiak@ipaper.com>, "Moreira, Dave"



9768983

<Dmoreira@wm.com>, John Laplante <jlaplante@anchoragea.com>, Wendell Mears <wmears@anchoragea.com>, Holly Samaha <hsamaha@anchoragea.com>, Rick Coupe <rcoupe@anchoragea.com>, "Leos, Valmichael" <Leos.Valmichael@epa.gov>, "Sanchez, Carlos" <sanchez.carlos@epa.gov>, "Meyer, John" <Meyer.John@epa.gov>, Satya Dwivedula <satya.dwivedula@tceq.texas.gov>, Bob Allen <bob.allen@pcs.hctx.net>, Linda Henry <lhenry@poha.com>, Garry McMahan <gmcghan@poha.com>, "Leah Oberlin (loberlin@poha.com)" <loberlin@poha.com>, "Foster, Anne" <Foster.Anne@epa.gov>, "Walters, Donn" <walters.donn@epa.gov>

Subject: FW: San Jacinto Maintenance Work Plan

David,

The EPA has reviewed and approves the attached work plan. As we discussed, the work will begin on March 22, 2016, and will take one to two days to complete.

Regards,

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov

From: David Keith [<mailto:dkeith@anchoragea.com>]

Sent: Monday, March 21, 2016 5:19 PM

To: Miller, Garyg <Miller.Garyg@epa.gov>

Cc: Phil Slowiak <philip.slowiak@ipaper.com>; Dave Moreira (dmoreira@wm.com) <dmoreira@wm.com>; John Laplante <jlaplante@anchoragea.com>; Wendell Mears <wmears@anchoragea.com>; Holly Samaha <hsamaha@anchoragea.com>; Rick Coupe <rcoupe@anchoragea.com>; Leos, Valmichael <Leos.Valmichael@epa.gov>

Subject: San Jacinto Maintenance Work Plan

Gary – As discussed, please review the attached subject document. With your approval we would like to start this work tomorrow morning. Please don't hesitate to contact me if you would like to discuss anything.

Thank you,
David

David Keith
Anchor QEA, LLC
614 Magnolia Avenue
Ocean Springs, MS 39564

Phone: 228-220-1156
Cell: 228-224-2983

dkeith@anchorgea.com

ANCHOR QEA, LLC

www.anchorgea.com

Please consider the environment before printing this email.

This electronic message transmission contains information that may be confidential and/or privileged work product prepared in anticipation of litigation. The information is intended for the use of the individual or entity named above. If you are not the intended recipient, please be aware that any disclosure, copying distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us by telephone at (228) 818-9626.

<Work Plan for Additional Rock Placement_March 2016.pdf>